


Sitka Airport

Pavement Condition Index - PCI Measured Values for the Year 2002

Airport Code: SIT
Site No.: 50703.*A



PCI Values General Pavement Recommendations

85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct


[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60

Sitka Airport


Pavement Condition Index - PCI Predicted Values for the Year 2003

Airport Code: SIT
Site No.: 50703.*A



[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60




PCI Values		General Pavement Recommendations
85 - 100	Preventative Maintenance	
70 - 84	Preventative / Corrective Maintenance	
60 - 69	Corrective Maintenance / Overlay	
55 - 59	Overlay / Rehabilitate	
40 - 54	Rehabilitate	
25 - 39	Reconstruct	
10 - 24	Reconstruct	
0 - 9	Reconstruct	

Sitka Airport

Pavement Condition Index - PCI Predicted Values for the Year 2004

Airport Code: SIT
Site No.: 50703.*A



[] Branch - Section Identifier


Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60

PCI Values		General Pavement Recommendations
85 - 100	Preventative Maintenance	
70 - 84	Preventative / Corrective Maintenance	
60 - 69	Corrective Maintenance / Overlay	
55 - 59	Overlay / Rehabilitate	
40 - 54	Rehabilitate	
25 - 39	Reconstruct	
10 - 24	Reconstruct	
0 - 9	Reconstruct	

Sitka Airport


Pavement Condition Index - PCI Predicted Values for the Year 2005

Airport Code: SIT
Site No.: 50703.*A



[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60




PCI Values		General Pavement Recommendations
85 - 100	Preventative Maintenance	
70 - 84	Preventative / Corrective Maintenance	
60 - 69	Corrective Maintenance / Overlay	
55 - 59	Overlay / Rehabilitate	
40 - 54	Rehabilitate	
25 - 39	Reconstruct	
10 - 24	Reconstruct	
0 - 9	Reconstruct	

Sitka Airport

Pavement Condition Index - PCI Predicted Values for the Year 2006

Airport Code: SIT
Site No.: 50703.*A



[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60


PCI Values General Pavement Recommendations

85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

Sitka Airport


Pavement Condition Index - PCI Predicted Values for the Year 2007

Airport Code: SIT
Site No.: 50703.*A



[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60




PCI Values		General Pavement Recommendations
85 - 100	Preventative Maintenance	
70 - 84	Preventative / Corrective Maintenance	
60 - 69	Corrective Maintenance / Overlay	
55 - 59	Overlay / Rehabilitate	
40 - 54	Rehabilitate	
25 - 39	Reconstruct	
10 - 24	Reconstruct	
0 - 9	Reconstruct	

Sitka Airport


Pavement Condition Index - PCI Predicted Values for the Year 2008

Airport Code: SIT
Site No.: 50703.*A



[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



PCI Values		General Pavement Recommendations
85 - 100	Preventative Maintenance	
70 - 84	Preventative / Corrective Maintenance	
60 - 69	Corrective Maintenance / Overlay	
55 - 59	Overlay / Rehabilitate	
40 - 54	Rehabilitate	
25 - 39	Reconstruct	
10 - 24	Reconstruct	
0 - 9	Reconstruct	